

## **Public Works Report March 2009**

- Ditch repair to 194 Harpeth Hills Drive. Ditch had no drainage , water backing up in the yard.
- Replaced 11 of the 12 Main Street lights with pulse bulbs. The lights were installed with probe bulbs , the ballast calls for a pulse bulb.
- Installed new bulb on the west bound red light.
- Called a Tn. One call for two locations on Harpeth View Trail . There are two sink holes over two different culverts.
- Removed fallen tree @ East K.S. road.
- Replaced street signs @ Timber Ridge and City Limits on Brush Creek Road.

## **Sewer Report March 2009**

- Septic tanks pumped – 204 Hickory Drive , 405 Harpeth Meadows Drive , 312 West View Drive and 484 Old Barn Trace.
- After pumping the tank at 312 West View , I told the owner the needed to be replaced due to blockage and leaks.
- Pump repair @ 464 Old Barn Trace.
- Attended a three day on Biological Natural Systems at Fleming Training Center.
- Installed new pumps , panels and plumbing @ West K.S. road , Cemetery Road , Bateman and Arrowhead Court sewer pump stations. This completes all of the under ground stations.
- Septic tank repair on Park Street.